

VIRGINIA **DIVISION OF HISTORIC LANDMARKS**

File no. 76-338 Negative no(s). 9674-12, 15

HISTORIC DISTRICT/BRIEF SURVEY FORM

Historic name Present use Residence	Road U.S.G.S. Quad Nokesville Common name
Present use Residence Priginal use Residence	Building Style Vernacular Building Date(s) 1890-1920
. Construction Materials	3. Stories (number)
✓ wood frame	□ low basement □ raised basement 4. Bays (number): front □ side (church) □
bond: ☐ English ☐ Flemish	symmetrical asymmetrical
□course American □ stretcher □ other	5. Roof Type □ shed □ parapet? □ pyramidal?
stone random rubble coursed rubble ashlar dressed log: squared unsquared notching: V-notch half dovetail saddle full dovetail square diamond concrete block terra cotta steel frame other Cladding Material weatherboard composition siding stucco board & batten aluminum or vinyl siding sheet metal diasbestos enameled metal glass bricktex other	gable mansard false mansard gambrel gambrel flat cross gable? parapet? parapet? parapet? parapet? parapet? parapet? parapet? ocentral front gable? roof not visible other
	6. Roofing Material □ shingle □ composition (asphalt, asbestos, etc.) □ wood □ metal □ standing seam
	☐ corrugated ☐ pressed tin (simulated shingles) ☐ tile ☐ pantile ☐ flat ☐ glazed ☐ slate ☐ not visible
	7. Dormers (number): front side gable
	8. Primary Porch style
	9. General supplementary description and decoration: 2/2 sash; boxed cornice; east end bay.
From Whitzels.	10. Major additions and alterations: Asbestos shingles added; plastic shutters added; rear 2-story ell; rear 1-story side porch (closed in).

□ steel frame □ other	✓ metal ✓ standing seam
weatherboard	☐ corrugated ☐ pressed tin (simulated shingles) ☐ tile ☐ pantile ☐ slate ☐ not visible 7. Dormers (number): front side ☐ gable ☐ pediment? ☐ shed ☐ hipped 8. Primary Porch
	style Vernacular stories 1 levels 1 bays 3 materials Wood description and decorative details Hipped roof, turned posts; entrance has been changed to the side; screened in.
	9. General supplementary description and decoration: 2/2 sash; boxed cornice; east end bay.
	10. Major additions and alterations: Asbestos shingles added; plastic shutters added; rear 2-story ell; rear 1-story side porch (closed in).
	II. Outbuildings: Washhouse, garage, small barn, workshop, and hen house.
	12. Landscape Features: Mature trees and shrubs. Chain link fence.
	13. Significance:
	Turn-of-the-century dwelling. One of several in the settlement of Brentsville.
	HEN HOUSE
	Surveyed by: Frazier Date: May 1989



