


de 1451V metreatut VIRGINIA DIVISION OF HISTORIC LANDMARKS


File no. 76–338 / Negative no(s). 9674–17, 18

HISTORIC DISTRICT/BRIEF

City/Town/Village/Hamlet Brentsville Street address or route number 12232 Bristow F Historic name	County Prince William County Road U.S.G.S. Quad Nokesville Common name		
Present use Residence	Building Style Vernacular		
Original use Residence	Building Date(s) 1880–1900		
Date June 7, 1989			
Construction Materials	3. Stories (number)2		
Naume	☐ low basement ☐ raised basement		
₩ wood frame			
□ brick	4. Bays (number): front8 side (church)		
bond: English	□ symmetrical ☑ asymmetrical		
Flemish	5 D CD		
course American	5. Roof Type		
stretcher	□ shed □ hipped		
stone other	parapet? pyramidal? gable systic box anombbs assume mansard 4) golesof box as 41		
☐ random rubble	☐ pediment? ☐ false mansard		
□ coursed rubble	☐ parapet? ☐ gambrel		
□ ashlar □ dressed	□ clipped end? □ flat		
□ rock-faced	□ cross gable? □ parapet?		
□ log:	☐ central front gable? ☐ roof not visible		
□ squared □ unsquared	Other		
notching:	tale to enime of Plan		
□ V-notch □ half dovetail	6. Roofing Material		
□ saddle □ full dovetail			
□ square □ diamond	☑ shingle ☑ composition (asphalt, asbestos, etc.) -side wing		
□ concrete block			
☐ terra cotta	∠ wood		
□ steel frame	☑ metal		
Other	☐ standing seam		
	□ corrugated		
	pressed tin (simulated shingles)		
2. Cladding Material	□ tile		
The second of th	☐ pantile ☐ glazed		
weatherboard composition siding	□ slate		
□ vertical siding □ stucco	□ not visible		
□ board & batten □ aluminum or vinyl siding			
☐ shingle: ☐ cast iron	7. Dormers (number):side		
□ wood □ sheet metal	☐ gable ☐ pediment?		
□ asbestos □ enameled metal	□ shed		
☐ asphalt ☐ glass ☐ bricktex	hipped		
□ other	0 D' D 1		
- Odici	8. Primary Porch		
	style1		
	5		
	levels bays bays bays		
	description and decorative details rectangular posts, sawn brackets, and		
	stone floor.		
	9. General supplementary description and decoration: 6/6 sash,		
Overed by Hadehier's Mesonal	boxed cornice, 2 front entrances with another		
	entrance on the side wing; cornerboards; brick		
	end flue; louvered shutters. 10. Major additions and alterations:		
	10. Major additions and alterations: Many shutters are missing; west side has a one		
Anne Keys, OTOHOJ time resi-	story wing with 3 bays; rear one story ell.		
	" "		

□ steel frame	™ metal	
□ other	☐ standing seam	
	☐ corrugated	
	pressed tin (simulated shingles)	
2. Cladding Material	□ tile □	D-111
weatherboard composition siding	☐ pantile ☐ flat ☐ slate	□ glazed
✓ weatherboard ☐ composition siding ☐ vertical siding ☐ stucco	□ not visible	
□ board & batten □ aluminum or vinyl siding	in not visitive	
☐ shingle: ☐ cast iron	7. Dormers (number): front side	•
□ wood □ sheet metal	☐ gable ☐ pediment?	
☐ asbestos ☐ enameled metal	□ shed	
□ asphalt □ glass	☐ hipped	
□ bricktex		
other	8. Primary Porch Vernacular	
	style vernacular stories	
	levels 1	bays 5
	materials wood	ouys
	description and decorative details rectangular posts, sawn	
	rectangular posts, sawn	brackets, and
	stone floor.	WATER 100
		Steich of Sile Flag
	9. General supplementary description and de	
Owned by Batcher's Memorial	boxed cornice, 2 front entra	
	entrance on the side wing; o	
	end flue; lowered shutters: 10. Major additions and alterations:	0.1212
Anne Keyer OlOHQ Fine cest-	Many shutters are missing; w	west side has a one
dent of Brentsville says that	story wing with 3 bays; rear	one story ell.
	II. Outbuildings	
	11. Outbuildings:	
	191 11	
	12. Landscape Features:	
	Mature Walnut and maple	trees.
	13. Significance:	
	Typical frame, vernacular dwel	ling built in the
	late 19th century.	IIIIg Salle III elle
	Surveyed by:	Date:
	Frazier	May 1989





1RBEE /

BAI