

VIRGINIA **DIVISION OF HISTORIC LANDMARKS**


File no. 76-338


Negative no(s)9675-16,17, 18,19


HISTORIC DISTRICT/BRIEF SURVEY FORM

City/Town/Village/Han Street address or route no Historic name	nlet Brentsville umber 12309 Bristow F	County Prince William County U.S.G.S. Quad Nokesville Common name
Present use Residence Original use Residence		Building Style Bungalow Building Date(s) ca. 1940 - 1948
I. Construction Materials wood frame brick English Flemish -course American stretcher other coursed rubble ashlar dressed rock-faced log: squared notching: V-notch half dovetail saddle full dovetail square diamond concrete block foundation terra cotta steel frame other		3. Stories (number) 1 1/2 ☐ raised basement ☐ raised basement
		4. Bays (number): front3 side (church) ✓ symmetrical □ asymmetrical
		5. Roof Type shed
		□ cross gable? □ parapet? □ central front gable? □ roof not visible □ other □ contral front gable? □ roof not visible
		6. Roofing Material Shingle Composition (asphalt, asbestos, etc.) wood metal standing seam corrugated pressed tin (simulated shingles)
2. Cladding Material ☐ weatherboard ☐ vertical siding	□ composition siding □ stucco	☐ tile ☐ pantile ☐ flat ☐ glazed ☐ slate ☐ not visible
 □ board & batten □ shingle: □ wood □ asbestos □ asphalt □ bricktex 	☐ aluminum or vinyl siding ☐ cast iron ☐ sheet metal ☐ enameled metal ☐ glass	7. Dormers (number): front _1 side ☐ gable ☐ pediment? ☐ shed ☐ hipped
□ other		8. Primary Porch style Vernacular stories 1
		levels 1 bays 5 materials wood description and decorative details House roof extends over the porch and is supported by six square wooden posts. Plain
		9. General supplementary description and decoration: 2/2 sash. Enclosed side porch.
		10. Major additions and alterations:
РНОТО		Ell and enclosed porch on back.

☐ terra cotta		LJ wood	
☐ steel frame		□ metal	
other		☐ standing seam	
		☐ corrugated	
		□ pressed tin (simulated shingles)	
2. Cladding Material		□ tile	
☐ weatherboard	☐ composition siding		
☐ vertical siding	stucco	not visible	
☐ board & batten	☐ aluminum or vinyl siding		
☑ shingle:	□ cast iron	/. Dormers (number): front side	
□ wood □ asbestos	☐ sheet metal		
	□ enameled metal		
☐ asphalt ☐ bricktex	□ glass	□ mpped	
other		8 Primary Porch	
- Other		style Vernacular	
		To	
		wood railing.	
		9. General supplementary description and decoration:	
		2/2 sash. Enclosed side porch.	
		10. Major additions and alterations:	
	РНОТО	Ell and enclosed porch on back.	
		11. Outbuildings:	
		Vertical boards on barn. Four sheds, one	
		metal standing seam corrugated pressed tin (simulated shingles) tile pantile flat glazed slate not visible	
		13. Significance:	
		only bungatow residence in BrentsVille.	
		0 0	
		BRISTON: Occ.	
		GROST W	
		Surveyed by:	
		Born May 1989	







Brentsville Presbyterian Church owns the property. Their drainage field is there.

The original owner built the shanty, behind the house, to living while the Bungalow was being built. The original owner raise chickens, goats and sheep. He sold goats milk.