



**VIRGINIA**  
**DIVISION OF HISTORIC LANDMARKS**  
**HISTORIC DISTRICT/BRIEF**  
**SURVEY FORM**

File no. 76-313  
Negative no(s). 9043

City/Town/Village/Hamlet Buckland County Prince William  
Street address or route number 8108 Buckland Mill Rd. U.S.G.S. Quad Thoroughfare Gap  
Historic name \_\_\_\_\_ Common name \_\_\_\_\_  
Present use \_\_\_\_\_ Building Style Vernacular  
Original use Residence Building Date(s) Ca. 1880; 1950s

1. Construction Materials

- ☒ wood frame  
☐ brick  
bond: ☐ English  
☐ Flemish  
☐ \_\_\_\_\_-course American  
☐ stretcher  
☐ other \_\_\_\_\_  
☐ stone  
☐ random rubble  
☐ coursed rubble  
☐ ashlar ☐ dressed  
☐ rock-faced  
☐ log:  
☐ squared ☐ unsquared  
notching:  
☐ V-notch ☐ half dovetail  
☐ saddle ☐ full dovetail  
☐ square ☐ diamond  
☐ concrete block  
☐ terra cotta  
☐ steel frame  
☐ other \_\_\_\_\_

2. Cladding Material

- ☒ weatherboard ☐ composition siding  
☐ vertical siding ☐ stucco  
☐ board & batten ☐ aluminum or vinyl siding  
☐ shingle: ☐ cast iron  
☐ wood ☐ sheet metal  
☐ asbestos ☐ enameled metal  
☐ asphalt ☐ glass  
☐ bricktex  
☐ other \_\_\_\_\_

3. Stories (number) 1-1/2  
☒ low basement ☐ raised basement

4. Bays (number): front 4 side (church) \_\_\_\_\_  
☐ symmetrical ☒ asymmetrical

5. Roof Type  
☐ shed ☐ hipped  
☐ parapet? ☐ pyramidal?  
☒ gable ☐ mansard  
☐ pediment? ☐ false mansard  
☐ parapet? ☐ gambrel  
☐ clipped end? ☐ flat  
☐ cross gable? ☐ parapet?  
☐ central front gable? ☐ roof not visible  
☐ other \_\_\_\_\_

6. Roofing Material

- ☒ shingle  
☒ composition (asphalt, asbestos, etc.)  
☐ wood  
☐ metal  
☐ standing seam  
☐ corrugated  
☐ pressed tin (simulated shingles)  
☐ tile  
☐ pantile ☐ flat ☐ glazed  
☐ slate  
☐ not visible

7. Dormers (number): front 2 side \_\_\_\_\_  
☒ gable ☐ pediment?  
☐ shed  
☐ hipped

8. Primary Porch

style Vernacular  
stories 1  
levels 1 bays 1  
materials concrete block; wood; asphalt shing  
description and decorative details  
Simple, square-post construction.

9. General supplementary description and decoration:

6 over 6 windows, modern shutters. Exposed  
rafter ends on dormers. Open side porch on  
south, closed ell on north.

10. Major additions and alterations:

E11 addition to north side.

11. Outbuildings:

None

12. Landscape Features:

Trees, bushes and grass

13. Significance:

An older house substantially  
remodeled, including a new foundation.  
A portion of the present building was moved  
to this site from 16280 Lee Hwy. ca. 1953.

Surveyed by: Marc C. Wagner

Date: Revised  
May 1987

