



**VIRGINIA**  
**DIVISION OF HISTORIC LANDMARKS**  
**HISTORIC DISTRICT/BRIEF**  
**SURVEY FORM**

File no. 76-313  
 Negative no(s). 9045

City/Town/Village/Hamlet Buckland  
 Street address or route number 16210 Lee Highway  
 Historic name \_\_\_\_\_

County Prince William  
 U.S.G.S. Quad Thoroughfare Gap  
 Common name Hazel House

Present use \_\_\_\_\_  
 Original use \_\_\_\_\_

Building Style Colonial Revival  
 Building Date(s) ca. 1950

**1. Construction Materials**

- ☐ wood frame  
☐ brick  
     bond: ☐ English  
           ☐ Flemish  
           ☐ \_\_\_\_\_-course American  
           ☐ stretcher  
           ☐ other \_\_\_\_\_
- ☐ stone  
     ☐ random rubble  
     ☐ coursed rubble  
     ☐ ashlar      ☐ dressed  
                   ☐ rock-faced
- ☐ log:  
     ☐ squared              ☐ unsquared  
     notching:  
     ☐ V-notch              ☐ half dovetail  
     ☐ saddle              ☐ full dovetail  
     ☐ square              ☐ diamond
- ☒ concrete block  
☐ terra cotta  
☐ steel frame  
☐ other \_\_\_\_\_

**2. Cladding Material**

None

- ☐ weatherboard      ☐ composition siding  
☐ vertical siding      ☐ stucco  
☐ board & batten      ☐ aluminum or vinyl siding  
☐ shingle:  
     ☐ wood              ☐ sheet metal  
     ☐ asbestos          ☐ enameled metal  
     ☐ asphalt           ☐ glass  
☐ bricktex  
☐ other \_\_\_\_\_

**3. Stories (number) 1-1/2**

- ☐ low basement              ☐ raised basement

**4. Bays (number): front 3 side (church) \_\_\_\_\_**

- ☐ symmetrical              ☐ asymmetrical

**5. Roof Type**

- ☐ shed                      ☐ hipped  
☐ parapet?              ☐ pyramidal?  
☒ gable                   ☐ mansard  
☐ pediment?           ☐ false mansard  
☐ parapet?              ☐ gambrel  
☐ clipped end?          ☐ flat  
☐ cross gable?          ☐ parapet?  
☐ central front gable?   ☐ roof not visible  
☐ other \_\_\_\_\_

**6. Roofing Material**

- ☒ shingle  
☐ composition (asphalt, asbestos, etc.)  
☐ wood  
☐ metal  
☐ standing seam  
☐ corrugated  
☐ pressed tin (simulated shingles)  
☐ tile  
☐ pantile                  ☐ flat                  ☐ glazed  
☐ slate  
☐ not visible

**7. Dormers (number): front 2 side \_\_\_\_\_**

- ☐ gable              ☐ pediment?  
☐ shed  
☐ hipped

**8. Primary Porch**

style no style  
 stories 1  
 levels 1 bays 3  
 materials wood, concrete block  
 description and decorative details  
plain, square posts, square wood bal-  
usters

**9. General supplementary description and decoration:**

Simple Cape Cod style concrete block cottage  
with ground level rear porch

**10. Major additions and alterations:**

None

**11. Outbuildings:**

None

**12. Landscape Features:** Driveway west of house is  
believed to be on site of early Buckland stree  
(Elizabeth Street). Traces of masonry foun-  
dation east of house.

**13. Significance:**

Noncontributing building

Surveyed by: James C. Massey

Date: May 1987

