

## VIRGINIA DIVISION OF HISTORIC LANDMARKS

File no. 76-313 Negative no(s). 9043901

## HISTORIC DISTRICT/BRIEF SURVEY FORM

City/Town/Village/Hamlet Buckland Street address or route number 8111 Buckland N	
Historic name Deerlick Cottage	Common name
Present use Residence Original use Residence and/or Store	Building Style Vernacular Building Date(s) Early - mid 18th century
Construction Materials	3. Stories (number) 1-1/2
	☐ low basement ☐ raised basement
☑ wood frame	4 D - (
□ brick bond: □ English	4. Bays (number): front side (church) Symmetrical ⊠ asymmetrical
□ Flemish	a asymmetrical
-course American	5. Roof Type
☐ stretcher	shed hipped
stone other	□ parapet? □ pyramidal? □ gable □ mansard
☐ random rubble	pediment?
□ coursed rubble	□ parapet? □ gambrel
□ ashlar □ dressed	☐ clipped end? ☐ flat
□ rock-faced	□ cross gable? □ parapet?
□ log: □ squared □ unsquared	☐ central front gable? ☐ roof not visible ☐ other ☐
notching:	Li otici
☐ V-notch ☐ half dovetail	Roofing Material
☐ saddle ☐ full dovetail	
☐ square ☐ diamond ☐ concrete block	⊠ shingle ⊠ composition (asphalt, asbestos, etc.)
terra cotta	wood wood
□ steel frame	□ metal
□ other	☐ standing seam
	corrugated
2. Cladding Material	☐ pressed tin (simulated shingles) ☐ tile
2. Clauding Hatteria	□ pantile □ flat □ glazed
★ weatherboard	□ slate
□ vertical siding □ stucco	not visible
☐ board & batten ☐ aluminum or vinyl siding ☐ shingle: ☐ cast iron	7. Dormers (number): front 2 side
□ wood □ sheet metal	7. Dormers (number): front side  ☑ gable □ pediment?
□ asbestos □ enameled metal	shed
☐ asphalt ☐ glass	□ hipped.
□ bricktex □ other	9 Drivers Deach
	8. Primary Porch style Vernacular
	stories1
	levels bays3
	materials Wood; asphalt tile; concrete
	description and decorative details Simple, 3-bay porch with fourth bay
	at north end enclosed; all bays covered by
	kick roof extension of main roof.
	<ol> <li>General supplementary description and decoration:</li> <li>Simple 1-1/2 -story frame dwelling over raised</li> </ol>
	basement. Large exterior chimney south end,
	stone to shoulder height, then brick. Smaller
	10. Major additions and alterations brick chimneys east and
PHOTO	One-story shed -roof addition at rear, with
	large, modern wood deck attached, both extending entire length of house.
	11. Outbuildings:
	One-story, 3-bay frame cabin with vertical
in process	board siding, gable roof, 3-bay front porch.
	Constructed ca. 1975 for storage.  12. Landscape Features:
	Post-and-rail fence encloses property on
	north, south and west sides, with Broad Run
	forming east boundary. Mature trees, shrubs,
	13. Significance: and extensive front and rear lawns.
	Early and important building in Buckland his-
	tory. Served as post office, store and distil-
	lery in mid-19th century.
	Surveyed by: Shirley Maxwell Date: May 1987

BUCKLAND HISTORIC DISTRICT Prince William County, VA

8111 Buckland Mill Rd. (Deerlick Cottage) Storage building (non-contributing) File #76-313 Neg. #9044(26)

