



**VIRGINIA**  
**DIVISION OF HISTORIC LANDMARKS**  
**HISTORIC DISTRICT/BRIEF**  
**SURVEY FORM**

File no. 76-313

Negative no(s). 9044

City/Town/Village/Hamlet Buckland County Prince William  
 Street address or route number 8200 Buckland Mill Rd. U.S.G.S. Quad Thoroughfare Gap  
 Historic name Trone, John, House Common name \_\_\_\_\_  
 Present use Residence Building Style Vernacular  
 Original use Residence Building Date(s) early 19th century

1. Construction Materials

- wood frame
  - brick
    - bond:  English
    - Flemish
    - \_\_\_\_\_-course American
    - stretcher
    - other \_\_\_\_\_
  - stone
    - random rubble
    - coursed rubble
    - ashlar  dressed
    - rock-faced
  - log:
    - squared  unsquared
    - notching:  V-notch  half dovetail
    - saddle  full dovetail
    - square  diamond
  - concrete block
  - terra cotta
  - steel frame
  - other \_\_\_\_\_

2. Cladding Material

- weatherboard  composition siding
- vertical siding  stucco
- board & batten  aluminum or vinyl siding
- shingle:  cast iron
- wood  sheet metal
- asbestos  enameled metal
- asphalt  glass
- bricktex
- other \_\_\_\_\_

3. Stories (number) 1-1/2  
 low basement  raised basement

4. Bays (number): front 3 side (church) \_\_\_\_\_  
 symmetrical  asymmetrical

5. Roof Type  
 shed  hipped  
 parapet?  pyramidal?  
 gable  mansard  
 pediment?  false mansard  
 parapet?  gambrel  
 clipped end?  flat  
 cross gable?  parapet?  
 central front gable?  roof not visible  
 other \_\_\_\_\_

6. Roofing Material  
 shingle  
 composition (asphalt, asbestos, etc.)  
 wood  
 metal  
 standing seam  
 corrugated  
 pressed tin (simulated shingles)  
 tile  flat  glazed  
 slate  
 not visible

7. Dormers (number): front 0 side 0  
 gable  pediment?  
 shed  
 hipped

8. Primary Porch 0  
 style \_\_\_\_\_  
 stories \_\_\_\_\_  
 levels \_\_\_\_\_ bays \_\_\_\_\_  
 materials \_\_\_\_\_  
 description and decorative details \_\_\_\_\_

9. General supplementary description and decoration:  
Small, plain frame dwelling above high stone basement. Large exterior brick chimney on south gable end.

10. Major additions and alterations:  
Two second-floor exterior doors to porch removed sometime after 1930 and openings converted to windows, east side (front).

11. Outbuildings:  
None

12. Landscape Features:  
Stone retaining wall on east side. Steeply sloping lot to west (rear) yard. Trees, shrubs, grass.

13. Significance:  
Believed to have been residence of John Trone, Buckland blacksmith and lay preacher prominent in community affairs before and during the Civil War.



Surveyed by: Shirley Maxwell

Date: May 1987