


Buckland Mill.

3d floor, scarf joint on long side of beams.  
hewn beams + sawed beams + uprights.

some Chestnut,



ends of  
tenon  
project  
part  
the post.


1st + 2d floor,

joint

clean sawed - circular saw marks.

In general,

14"



See Eric Sloan book  
for the name of  
this joint.

Notes 11/8

Buckland Mill. 1900?

Owner says that mill was powered  
by diesel engine from \_\_\_\_\_ to \_\_\_\_\_  
Prior to that a <sup>fell</sup> turbine (vertical?)  
ran the mill. Turbine was located  
underneath the mill + water  
was channelled or diverted to run  
it. Owner sold turbine for  
junk about 35-40 years ago.

1978  
40  
38  
# acres -  
date const. -  
operated until -  
Product(s)  
true?

Timber in mill supposedly came  
from earlier mill which was  
dismantled in \_\_\_\_?. Location?

<sup>elevators</sup>  
shafts, belts + wooden machinery  
remaining in the mill but not in  
use. Most of it is stored on 3d floor

Interior changed little, if any,  
except for removal of mill works.

Stuart owns creek to h.w. mark  
on other side.