

9/29/79

photographed 4898

Cedar Run Bridge on S.R. 611

on Fleetwood Drive.

Photographed this bridge 29 Sep. 1979

Bridge seems to be in fair condition.

Cars going over it though set up strong vibrations.

Mr. Gu said it was last painted in 1977.

Stone abutments

Plaque on west chord <sup>1900</sup> Walker Bros } BROKEN.  
Contractors }

Marine base is on west side of  
611 here.

as only a  
small part  
remaining.



611 cedar

Structure #6047

88 ft. long

11 ft clear roadway

weight limit = 8 Tons

Timber floor

last painted in 1973. Paint when necessary.

10 years or so between painting.