

MT. ATLAS (76-15) Mt. Atlas Lane, Haymarket, Va.
Prince William County

measured
11/9/78

Mr. + Mrs. Barton Padgett Thoroughfare Gap 7.5
4024 Mt. Atlas Lane Stereo 2
Haymarket, Va.

EXTERIOR

Rubble Stone found, ^{w 1 water table. becomes brick at shoulder} stone stack, ^{Modillion} ~~Box~~ cornice. ^{common bond}
Windows: 9/9, 6/6 sash. ^{Mitered corners.} Front door [panel?]
4 1/2" x 7' 3" (10' high including overhead 5-pane transom). Door has moulded cornice (see dwg.)

~~2 st. EL is of a later date. German siding on EL; plain on mt.~~

~~Painted cream yellow with brown trim.~~

c17x20 EL has 6-panel ^{ext} door with transom.

Said by owner to have been moved to this site as a 1 1/2-story weaving cottage + raised to 2-stories. c1910.

EL has German (channelled siding) on N. + west sides; plain siding on south side - S. side has a 1-st enclosed porch covered w/ German siding. and a one-story kitchen extension in the corner the south side EL makes with west side of main house.

see
dwg.

add
to main
blg.

1-story pillared porch on front, ^{main house} const. by owner's father ^{c1910.} Stone foundation - stones taken from kitchen dismantled nearby. ^{concrete floor, steps}
House painted yellow gold.

2 dormers in roof w/ plain gables + windows 6/6.

Outbldgs.

Heavy timber Post + Beam const. meat house, ^{c12'x12'} off back of el.

MT. ATLAS (76-15) cont.

meat house has pent roof (metal covered.)
5" lap siding. wide batten doors.
Stone foundation, dirt floor.

Interior

Woodwork

Mantel

dining room ^{2d fl.} upstairs right.

Cemetery? no, but writer's grave

mt. atlas, architecture.

41 1/2
35 1/2

Foundation under main home only, has walls

Basement, c 18" thick, constructed in two sections; providing extra support between stair hall and living room.

Heavy, hewn beams in basem. Large fireplace in cellar.

Shed roofed, 1 story entrance to basement constructed by present owner. Foundation needs repair, estimated by owner to be very expensive.

Exterior: Whole home formerly painted yellow-gold with brown trim.

Single, exterior, chimney with brick repair(?) from shoulder to top. Main house has c 5"-lap clapboards, ^{Stone} except for a small section of west side, which has channelled siding.

Modillion cornice, Architrave trim around windows, door. ~~Trim formerly painted brown.~~

Front porch constructed c 1910, using stones from demolished kitchen south of main house ^{for foundation}.
Dormers in roof added c 1910.

~~2-story ^{et} wing said to have been moved ^{to} to this site is a 1 1/2 story weaving cottage and raised to 2 stories.~~

~~1910~~ Two-story el ~~on rear~~ has channelled siding on North and west sides, plain ~~clapboard~~ weatherboards on south side. South side of el has a 1-story shed roof enclosed porch covered with channelled siding.

Note: ~~this~~ el has a 6-panel handmade door with ~~work~~ a ~~pill~~

