

Schoolhouse arch.

This is a one-room schoolhouse with 4"-lap weatherboard exterior, plain trim, exposed rafters, deep eaves, and cornerboards. There is a hood on brackets sheltering the front entrance, a 5-panel 20th century door with a 3-light overhead. There is a one-story shed-roofed addition across the rear of the schoolhouse, probably constructed in the 1960s. ~~Large~~ Five large $\frac{1}{6}$ sliding sash windows on the front light the classroom.

Inside there is a ~~large~~ classroom complete with blackboards to the left of the side passage. Behind the lobby is a cloak room which has been converted to a kitchen. There are two workrooms or office and two rest rooms in the recent addition.

The ceiling of the old school ~~has a~~ is pressed tin. The electric lights are fluorescent now, but fixtures for the old hanging lights still exist. An air conditioning and heating unit has been installed in a partitioned-off section on the classroom's east wall. The floors are narrow tongue and groove maple. The walls are covered with plaster and wallboard.

There is waist-high wainscoting (matchboard) in the foyer and ~~on the~~ classroom, while the wainscoting in the former cloak room is chest high. An entrance to the new addition

has been made on the north wall of the classroom. Here it is possible to see where the ~~door~~ wainscoting was cut, and the sill, door, and trim are new. The interior doors, ~~except~~ except for the utility room and the above-mentioned are 5-panel doors similar to the front door. The interior trim is plain box trim with rounded edges. All woodwork inside is painted light green.