

Monroe 5-3

(2)
81

Condition

North wall - sills rotted.

logs fair to good 70-80%?

plate rotten in 1 spot

joists 1st fl.

West wall

1 mile long log - bad on outside
all logs except sill are good from
inside.

Siding covers logs exterior.

North wall

West end is 90-100% bad. maybe some small
sections salvagable.

uppermost beam (sleeper?) is bad

interior wall is OK. (partition)

East wall seems OK.

Joists 1st floor

12 total?

maybe 7 are still usable
but prob not at the ends

Joists 2nd fl.

16 total.

24" on the ctr.

90-100% IIII III

70-80% IIII II

60% I


20%

0.

NOTE: FURNISHING
base of window
here is 9 inches
headed stepboard

Measure 5-3

Window
base for
6'6" 8'10"



per
window
to 5' high
head from
floor to top

3'1" 5'4" 12'6" 17'2 1/2 20'2"

join
between
2 rooms.

3'1" 5'5 3/4

30'2 1/2 to
end of logs
30'3 1/2 to end
of wall
incl siding

width
window
frame
outside dim

2'11" 5'6"

foundation 5' high
height sleepers to sill 7'9"

an
over
siding
window fr.