

Refined

in 1973 The Frame Shop.

before that Lynn Electric was in the
bldg.

asbestos siding on east side.

scalloped vergeboards.

shingles

2555555

plain frieze

box cornice?

shingles