


Ben Command store accessory P/dg.



ceiling height floor to ceiling = $7'9\frac{1}{2}"$
to joists $85-87"$

Antique Ben Leonard Stone accessory
bldg.




"NORTH ROOM" ^{walls}: Colors dusty, rose
possibly blue
ceiling: white over blue

"SOUTH ROOM"

Stay blue under all. ceiling +
walls.
then white

fireplaces blocked up with

lintel is
pegged
into wooden
shelf supporting
stone



2d floor.

rafters $4 \times 2\frac{1}{2}$ mortised & tenoned
& pegged.

signs of shingle roof evident
(pieces of shingle)

24" apart on ctr.

half-lapped collar beams.

cut nails in rafters

walls & ceiling white washed once.

cut nails in collar beams

"re-roofed 2 Jun 1950" inscribed
in replacement collar beams.

Shingles ^{I JC} off BL
LM
TC"

portl cement at gable ends
replacement or reinforcing rafters
at both gable ends.

stonework - break in stones on
portl. cement repointing

Floor 4' 1/2" wide tongue & groove
wire nails?

4-14

Ferry Klein arch recommendations:

Must get a crew in to look
at builders trench.

Road may hit possible trash
pile in back of house.

Call: No. Va. Chapter - Arch. Society of Va.

and 1 supv. or 2 supv.
need 10 people to dig for at least

long trenches or striping in back
only where road will be.

SITE PLAN

Mike Johnson cant do.

call Muller

call George Mason U. - they might do it

Call Tucker & say arch. been there &
prob. got entral.

No similar struc. has ever been seen
in this region. Put it on the registry

could do it separately.

Must have a supervisor.

See if county can take an easement,
or acquire.

Call Call Sara Bridges arch. ed.
Ray Luce arch. hist.

~~OAHF~~

possible. letter or telegram to
Church ~~asking for~~
stating arch + hist
importance

4-16

Spoke w/ Tucker. He said they hesitate to get
involved in county matter w/ owner.

Suggests writing inf. in a letter & send
immed. to him.