

**DIVISION OF HISTORIC LANDMARKS**  
**HISTORIC DISTRICT/BRIEF**  
**SURVEY FORM**

The no. 457 Negative no(s) 3635 (19)

76-457

City/Town/Village/Hamlet

Street address or route number

7479 Cerro Gordo Road

Historic name

(formerly part of Falkland)

County Prince William

U.S.G.S. Quad Thoroughfare Gap

Common name

Present use Residence

Original use Barn

Building Style Vernacular

Building Date(s) Ca. 1900

**1. Construction Materials**

☒ wood frame

☐ brick

bond: ☐ English

☐ Flemish

☐ \_\_\_\_\_course American

☐ stretcher

☐ other \_\_\_\_\_

☐ stone

☐ random rubble

☐ coursed rubble

☐ ashlar ☐ dressed

☐ rock-faced

☐ log:

☐ squared

☐ unsquared

notching:

☐ V-notch

☐ half dovetail

☐ saddle

☐ full dovetail

☐ square

☐ diamond

☐ concrete block

☐ terra cotta

☐ steel frame

☐ other \_\_\_\_\_

**2. Cladding Material**

☐ weatherboard

☐ composition siding

☐ vertical siding

☐ stucco

☒ board & batten

☐ aluminum or vinyl siding

☐ shingle:

☐ wood

☐ cast iron

☐ asbestos

☐ sheet metal

☐ asphalt

☐ enameled metal

☐ bricktex

☐ glass

☐ other \_\_\_\_\_

3. Stories (number) 2 (no basement)

☐ low basement

☐ raised basement

4. Bays (number): front 10 side (church) \_\_\_\_\_

☐ symmetrical

☒ asymmetrical

5. Roof Type

☐ shed

☐ hipped

☐ parapet?

☐ pyramidal?

☒ gable

☐ pediment?

☐ mansard

☐ parapet?

☐ false mansard

☐ clipped end?

☐ gambrel

☐ cross gable?

☐ flat

☐ central front gable?

☐ parapet?

☐ other \_\_\_\_\_

☐ roof not visible

**6. Roofing Material**

☐ shingle

☐ composition (asphalt, asbestos, etc.)

☐ wood

☒ metal

☒ standing seam

☐ corrugated

☐ pressed tin (simulated shingles)

☐ tile

☐ pantile

☐ flat

☐ glazed

☐ slate

☐ not visible

7. Dormers (number): front 0 side 0

☐ gable

☐ pediment?

☐ shed

☐ hipped

**8. Primary Porch**

style Vernacular

stories 1

levels 1

bays 8 (temporary posts)

materials wood, asphalt shingles

description and decorative details

Modern; just recently constructed, owner has not put in permanent porch supports as of the date of this survey.

9. General supplementary description and decoration: 2 square cupolas with gable roofs, 2 ceramic tile silos (dark brown), numerous access doors, large opening with semi-circular top (no windows yet)

10. Major additions and alterations:

Some new

fenestration.

**11. Outbuildings:**

None

**12. Landscape Features:**

Trees, bushes and pasture land.

**13. Significance:**

Until this lot was sold, the barn belonged to the Falkland Estate on which are two nearly identical barns from the same period. The present owner has knowledge of an archeological site, a worker's building on the property.

Surveyed by:

Marc C. Wagner

Date:

7/24/86

