MILLOMA DIVISION OF HISTORIC LANDMARKS

гие по. 76-168 Negative no(s). 8817

SURVEY FORM

Common name

Braymer Fouse

County/Town/City Prince William County

Street address or route number Rt. 29, Manassas National Battlefield Park

Gainesville **USGS Quad** Original owner

Historic name "Douglas Hall"

Original use Residence/farm

Present owner National Park Service

Present owner address Manassas National Battle-Source of date

field Park, Manassas, VA

Present use

Acreage

Historic site, vacant

Date or period Circa 1904, part is earlier

Architect/builder/craftsmen

Source of name National Park Service

National Park Service Stories

Foundation and wall const'n stone, frame, part is post-and-

beam

Roof type Metal gable

State condition of structure and environs Poor

State potential threats to structure

Note any archaeological interest

site being excavated by National Park Service behind the west

kitchen wing

Should be investigated for possible register potential? yes □ no □

Architectural description (Note significant features of plan, structural system and interior and exterior decoration, taking care to point out aspects not visible or clear from photographs. Explain nature and period of all alterations and additions. List any outbuildings and their approximate ages, cemeteries, etc.)

The existing structure at "Douglas Hall" is the result of a circa 1904 remodeling which encased the earlier post-and-beam farmhouse. Standing today is a 3 bay, 2 story, L-shaped structure with a metal gable roof, plain weatherboards, a simple cornice with returns, 2/2 sashes and plain cornerboards. There is a central flu in the south wing, and two end, interior flus in the north wing. The entry hall has a cellar beneath it.

Inside, the large central entry hall has a partially enclosed stair with a landing and a vertically paneled wall. The enclosed stair with winders, off the kitchen, has possibly been reversed. Facings throughout are symmetrical with cornerblocks, and the baseboard is tall and molded. The doors are a 4-paneled type, and the pine flooring measures $3\frac{1}{2}$ - 4" wide.

The side has a garage, an outbuilding, and the sites of two collapsed outbuildings. An earlier structure of wing has been excavated by the National Park Service directly behind the west wing.

> See also Douglas Hall Historic Structures Report VA 363.69 HIL

Interior inspected? No. Interior details taken from historic structures report.


Historical significance (Chain of title; individuals, families, events, etc., associated with the property.)

The Douglas family owned the farm but rented it to the Brawner family during the Civil War. The house overlooks the Warrenton turnpike to the south and was the site of the first major engagement of the "Second Battle of Manassas" in which over 1400 soldiers from both sides died. The Southern troops were led by Stonewall Jackson. The battle took place on August 28, 1862.


Published sources (Books, articles, etc., with bibliographic data.) "Douglas Hall" - Historic Structures Report

Manassas National Battlefield Park. Narional Park Service. National Capitol Region, Washington, C. C.

Primary sources (Manuscript documentary or graphic materials; give location.)



Site plan (Locate and identify outbuildings, dependencies and significant topographical features.)



Date 6/87 File No. 76-168

Name Brawner House

Town Manassas Battlefield

County Prince William County

Photographer B. Polhill

Contents 1 Exterior

Brawner House

North Facade



