VIRGINIA DIVISION OF HISTORIC LANDMARKS

File no. 76-313 Negative noisi, 9043

HISTORIC DISTRICT/BRIEF SURVEY FORM

| digress or route number 810 c name Buckland Taver | 6 Buckland Mill Rd. LS.G.S. Quad Thoroughfare Gap |
|--|---|
| Residence Residence or T | Building Style Vernacular Building Date(s) 1st gtr. 19th century |
| Struction Materials | 3. Stories (number)2 ≡ low basement |
| X red frame | 2 Bays (number) front3side (entireft) Z symmetrical X asymmetrical |
| X stone X random rubble Coursed rubble Cashlar Colorsed rubble Cashlar Coursed rubble Course rubb | □ shed □ hipped |
| Ty-notch | d 6. Rooting Material X shingle |
| X weatherboard | residing = |
| hiro tex when | 8. Primary Porch 0 style stories bays materials description and decorative details |
| | 9. General applementary description and decoration: Entrance stoop with iron railing, reached by high stone steps. Plain cornice. Large brick chimney north-gable end; smaller 10. Maker additions and alterations brick chimney on wing. 2-story frame addition at rear (west) side. |
| | Log cabin moved to site in 1973, 10'x12'. 2 dilapidated vertical-board storage buildings, 1 gable-roofed, 1 shed-roofed. 12 Lind are returns. Small front and south side yards, spacious north side yard, steeply sloping rear yard. Large trees, shrubs, grass. Its pivotal location at the |
| | intersection of Buckland Mill Road with the Lee Highway, as well as its 19th-century use as a tavern, make this a major feature of the Buckland Historic District. |

BUCKLAND HISTORIC DISTRICT Prince William County, VA 8106 Buckland Mill Rd. Outbuildings File # 76-313 Neg. #9044 (23)

