



DIVISION OF HISTORIC LANDMARKS
HISTORIC DISTRICT/BRIEF
SURVEY FORM

File No. 76-464
 Negative no(s) 8642 (9)

City/Town/Village/Hamlet _____ County Prince William
 Street address or route number 1/2 mile South of Haymarket U.S.G.S. Quad _____
 Historic name on west side of James Madison Common name Thoroughfare Gap
 Present use None Highway _____ Building Style _____
 Original use Farm access road, possible building site Building Date(s) _____

1. Construction Materials

wood frame
 brick
 bond: English
 Flemish
 _____-course American
 stretcher
 other _____

stone
 random rubble
 coursed rubble
 ashlar dressed
 rock-faced

log:
 squared unsquared
 notching:
 V-notch half dovetail
 saddle full dovetail
 square diamond

concrete block
 terra cotta
 steel frame
 other _____

3. Stories (number) _____
 low basement raised basement

4. Bays (number): front _____ side (church) _____
 symmetrical asymmetrical

5. Roof Type
 shed hipped
 parapet? pyramidal?
 gable mansard
 pediment? false mansard
 parapet? gambrel
 clipped end? flat
 cross gable? parapet?
 central front gable? roof not visible
 other _____

6. Roofing Material

shingle
 composition (asphalt, asbestos, etc.)
 wood
 metal
 standing seam
 corrugated
 pressed tin (simulated shingles)

tile
 pantile flat glazed
 slate
 not visible

7. Dormers (number): front _____ side _____
 gable pediment?
 shed
 hipped

8. Primary Porch
 style _____
 stories _____
 levels _____ bays _____
 materials _____
 description and decorative details _____

9. General supplementary description and decoration:

10. Major additions and alterations:

11. Outbuildings:

12. Landscape Features:

13. Significance: The rubble is comprised of wood and standing seam metal that dates, at least, to the early 20th-century. Potential artifacts.



Surveyed by: Marc C. Wagner Date: 7/25/86