

street address

Emma Jane Saxe

permission to inspect
verbal boundary description

take photos?

79 photos are ok.

5x7 or 8x10

NO interiors

trying to

TEXT. cut down on written part.

summary # in both sections
that expresses why it is sign.
in terms of NR criteria.

- Then elaborate if necessary.

↳ on a deteriorated bldg.

put
in
part 7.

the integrity should be addressed
structural soundness?

↳ roof is ok, though.

deteriorat, or that's

visual should be photographed.

site plan? include boundary justif.
or acreage justif.

Int.

One source says Camp Walker (conf. campsite) was located in house's front yard. In his book on Pr. William County, J. Ratcliffe says house was located between 2 Confederate campsites during Civil War. House was supposedly damaged during fighting.

Part of house dates to 1855, according to one source.

Blooms there before ^{the} Corners.

Arch:

Signs of ~~the~~ 2-story demolished el on back of house. Exterior may have once been ~~pan~~ white washed.

Doors, date to c 1905 - double, 4-panel front + back, 3 pane arch over door, front + back

House has a Full Basement.

Main house has moulded cornice, steeply pitched roof. ^{Smaller} section has box cornice, less steeply pitched roof.

6' x 11' concrete slab behind house (S.W. corner)

House is now surrounded by high, wire fence.

Mrs. Graver has the novel post. fancy.
 lie in manassas.

Mr. Murphy + his daughter no mantels
 have a lot of inf.

House is now surrounded by high wire fence.