



HERNDON HOUSE 76-117

PROP. PROJ. 0215-076-101



**ROAD CLASSIFICATION**

Primary highway, all weather, hard surface —————  
 Secondary highway, all weather, hard surface ————  
 Light-duty road, all weather improved surface - - - - -  
 Unimproved road, fair or weather ————  
 U. S. Route (rectangle symbol)  
 State Route (circle symbol)



MAP ACCURACY STANDARDS  
 U.S. GEOLOGICAL SURVEY, WASHINGTON, D. C. 20242  
 U.S. GEOLOGICAL SURVEY, CHARLOTTESVILLE, VIRGINIA 22903  
 ADDITIONAL INFORMATION AND SYMBOLS IS AVAILABLE ON REQUEST

Revisions shown in purple compiled in cooperation with Commonwealth of Virginia agencies from aerial photographs taken 1972. This information not field checked

**THOROUGHFARE GAP,**  
 3845—W7737.5/7.5  
 1966  
 PHOTOREVISED 1972  
 AMS 5461 1 SW—SERIES V834