

**Virginia Department of Historic Resources
Reconnaissance Level Survey**

HISTORIC SITE FILE: *Thoroughfare*
PRINCE WILLIAM PUBLIC LIBRARY SYSTEM
RELIC/Bull Run Reg Lib, Manassas, VA

DHR ID#: 076-0595

Other DHR ID#:

Resource Information

Resource Name(s): House, 16305 Thoroughfare Road, Route 682
{Current}
Date of Construction: ca 1900
Local Historic District:

National Register Eligibility Status

Resource has not been evaluated.*

Location of Resource

Commonwealth of Virginia
County/Independent City: Prince William
Magisterial District:
Town/Village/Hamlet: Thoroughfare
Tax Parcel:
Zip Code: 20169
Address(s): 16305 Thoroughfare Road, Route 682 {Current}
USGS Quadrangle Name: THOROUGHFARE GAP
UTM Boundary Coordinates:

* Resource has not been formally evaluated by DHR or eligibility information has not been documented in DSS at this time.

	<u>NAD</u>	<u>Zone</u>	<u>Easting</u>	<u>Northing</u>
UTM Center coordinates:		18	267840	4299680
UTM Data Restricted?:	No			

Resource Description

Ownership Status: Private
Government Agency Owner:
Acreage:
Surrounding area: Rural
Open to Public: No
Site Description:

The house is enclosed by a barbed wire fence and surrounded by a wooded area. There is a long driveway which circles around the main house.

Secondary Resource Summary:

The garage is southeast of the main house. The two sheds were behind the house.

Individual Resource Information

<u>Count</u>	<u>Resource Types</u>	<u>Resource Status</u>
1	Single Dwelling	Contributing
2	Shed	Contributing
1	Privy	Contributing
1	Animal Shelter/Kennel	Contributing
3	Foundation	Contributing

Individual Resource Detail Information

Resource Type:	Shed	Primary Resource?	No
Date of Construction:	9999	Accessed?	Not Evaluated
Architectural Style:		Number of Stories:	0.0
Form:		Condition:	
Interior Plan Type:		Threats to Resource:	None Known

**Virginia Department of Historic Resources
Reconnaissance Level Survey**

DHR ID#: 076-0595

Other DHR ID#:

Deterioration

The structure consists of a wooden frame shed with metal roofing. Abandoned farm machinery lay nearby.

Individual Resource Detail Information

<i>Resource Type.</i>	Foundation	<i>Primary Resource?</i>	No
<i>Date of Construction:</i>	9999	<i>Accessed?</i>	Not Evaluated
<i>Architectural Style:</i>		<i>Number of Stories:</i>	0.0
<i>Form:</i>		<i>Condition:</i>	Ruinous
<i>Interior Plan Type:</i>		<i>Threats to Resource:</i>	None Known Deterioration

The structure consists of a circa 45 by 30 foot cement wall which protrudes approximately 6 inches above the ground surface. A poured cement foundation, raised one-half foot above the ground surface, covered half of the structure. Some cement supports were present in the center and the structure appeared to have been frame. Wooden siding lay nearby. This may represent the remains of a barn. A livestock loading pen area constructed of flat board fencing lay to the east.

Individual Resource Detail Information

<i>Resource Type.</i>	Animal Shelter/Kennel	<i>Primary Resource?</i>	No
<i>Date of Construction:</i>	9999	<i>Accessed?</i>	Not Evaluated
<i>Architectural Style:</i>		<i>Number of Stories:</i>	0.0
<i>Form:</i>		<i>Condition:</i>	Poor
<i>Interior Plan Type:</i>		<i>Threats to Resource:</i>	Deterioration

The structure consists of a low cement structure with a wooden superstructure and metal roofing. It may be a livestock feeding pen.

Individual Resource Detail Information

<i>Resource Type.</i>	Privy	<i>Primary Resource?</i>	No
<i>Date of Construction:</i>	9999	<i>Accessed?</i>	
<i>Architectural Style:</i>		<i>Number of Stories:</i>	0.0
<i>Form:</i>		<i>Condition:</i>	Poor
<i>Interior Plan Type:</i>		<i>Threats to Resource:</i>	Deterioration

The structure is painted red with vertical wood siding.

Individual Resource Detail Information

<i>Resource Type.</i>	Foundation	<i>Primary Resource?</i>	No
<i>Date of Construction:</i>	9999	<i>Accessed?</i>	Not Evaluated
<i>Architectural Style:</i>		<i>Number of Stories:</i>	0.0
<i>Form:</i>		<i>Condition:</i>	Ruinous
<i>Interior Plan Type:</i>		<i>Threats to Resource:</i>	Deterioration

This structure consists of a dry-laid fieldstone foundation which measures circa 15 by 10 feet. An entrance is located on the east side and burned timbers were noted in the basement. Metal roofing was noted at the side of the structure.

Individual Resource Detail Information

<i>Resource Type.</i>	Shed	<i>Primary Resource?</i>	No
<i>Date of Construction:</i>	9999	<i>Accessed?</i>	Not Evaluated
<i>Architectural Style:</i>		<i>Number of Stories:</i>	1.0
<i>Form:</i>		<i>Condition:</i>	Poor
<i>Interior Plan Type:</i>		<i>Threats to Resource:</i>	None Known Deterioration

This is one-story storage shed which is covered with vertical wood siding and which has a metal roof. The structure was painted red.

**Virginia Department of Historic Resources
Reconnaissance Level Survey**

DHR ID#: 076-0595

Other DHR ID#:

Individual Resource Detail Information

<u>Resource Type.</u>	Dwelling/Store	<u>Primary Resource?</u>	Yes
<u>Date of Construction:</u>	ca 1900	<u>Accessed?</u>	Not Evaluated
<u>Architectural Style:</u>		<u>Number of Stories:</u>	2.0
<u>Form:</u>		<u>Condition:</u>	Poor
<u>Interior Plan Type:</u>		<u>Threats to Resource:</u>	Deterioration

This is a two-story frame structure with a one story addition. The structure is covered with vertical wood siding and has metal roofing and a central chimney. It measures 15 by 30 feet.

Individual Resource Detail Information

<u>Resource Type.</u>	Foundation	<u>Primary Resource?</u>	No
<u>Date of Construction:</u>	ca 1933 {Site Visit/Map}	<u>Accessed?</u>	No Not accessible
<u>Architectural Style:</u>		<u>Number of Stories:</u>	0.0
<u>Form:</u>		<u>Condition:</u>	Ruinous
<u>Interior Plan Type:</u>		<u>Threats to Resource:</u>	Deterioration

This structure measures circa 20 by 30 feet and consists of a mortared stone foundation with cement stairs on the west side. Metal roofing and burned timbers were noted in the vicinity. A brick chimney is present on the interior. A church is shown in this location on a 1933 map. A stone lined well with a cement cap and an open cistern are present to the northeast.

Primary Resource Exterior Component Description:

<u>Component</u>	<u>Comp Type/Form</u>	<u>Material</u>	<u>Material Treatment</u>
Roof	Roof - Gable	Wood	other
Chimneys	Chimneys - Interior	Brick	Chimneys, Cap, Corbeled
Foundation	Foundation - Solid/Continuous	Stone	Foundation - Rubble, Random
Porch	Porch - 1-story, 5-bay	Wood	other
Roof	Roof - Gambrel	Metal	Roof - Standing Seam
Structural System	Structural System - Frame	Wood	other
Windows	Windows - Sash, Double-Hung	Wood	Windows - 2/2

Historic Time Period(s): Q- World War I to World War II (1917-1945)

Historic Context(s): Domestic
Subsistence/Agriculture

Significance Statement

This early 20th century Colonial Revival dwelling is more unusual for the area; however, it does not appear to be potentially eligible for the National Register of Historic Places. At the time of 2003 investigation of the area, only a foundation remained of the dwelling.

National Register Eligibility Information (Intensive Level Survey):

<u>NR Count</u>	<u>NR Resource Type</u>	<u>NR Resource Status</u>
5	Building	Contributing
3	Site	Contributing
Contributing: 8		

National Register Criteria:

**Virginia Department of Historic Resources
Reconnaissance Level Survey**

DHR ID#: 076-0595

Other DHR ID#:

Period of Significance:

Level of Significance:

Graphic Media Documentation

<i>DHR Negative #</i>	<i>Photographic Media</i>	<i>Negative Repository</i>	<i>Photo Date</i>	<i>Photographer</i>
1	B&W 35mm Photos 35 mm b/w	VDHR	25, 1996 2003	76-595

Bibliographic Documentation

Cultural Resource Management (CRM) Events

CRM Event # 1,
Cultural Resource Management Event: Survey:Phase I/Reconnaissance
Date of CRM Event: 25, 1996
CRM Person: VCU-ARC Mary Ellen Bushey
VDHR Project ID # Associated with Event: VA Dept. of Transportation
CRM Event Notes or Comments:
 Project no. U000-155-V12, PE100 C-500

CRM Event # 2,
Cultural Resource Management Event: Survey:Phase I/Reconnaissance
Date of CRM Event: August 2003
CRM Person: Stephanie Taleff
CRM Event Notes or Comments:

CRM Event # 3,
Cultural Resource Management Event: Survey:Phase I/Reconnaissance
Date of CRM Event: April 2003
CRM Person: Joseph Blondino
CRM Event Notes or Comments:

Bridge Information

Cemetery Information

Ownership Information

Name: Richard Lanham
Title: Director of Planning
Company: KSI
Address: 8081 Wolftrap Rd.
 Suite 300
City: Vienna
Zip: 22182 *State:* Virginia *Country:* USA
Phone/Extension: 703-641-9000 / 0000
Relation to the Property: Property Manager
Miscellaneous Survey Notes: Did not enter property to l
 complete photography because of l
 no trespassing sign.