

DHR ID#: 076-0586

Other DHR ID#:

Resource Information

Resource Name(s): House, 6225 Thoroughfare Road, Route 682
 {Current}
 Date of Construction: ca 1900
 Local Historic District :

National Register Eligibility Status

Resource has not been evaluated.*

* Resource has not been formally evaluated by DHR or eligibility information has not been documented in DSS at this time.

Location of Resource

County/Independent City: Commonwealth of Virginia
 Prince William
 Magisterial District:
 Town/Village/Hamlet: Thoroughfare
 Tax Parcel:
 Zip Code:
 Address(s): Thoroughfare Road, Route 682 {Current}
 USGS Quadrangle Name: THOROUGHFARE GAP
 UTM Boundary Coordinates :

NAD Zone Easting Northing

UTM Center coordinates :
 UTM Data Restricted?.

Resource Description

Ownership Status:
 Government Agency Owner:
 Acreage:
 Surrounding area: Rural
 Open to Public:
 Site Description:

The house sits in an open field north of the railroad tracks. 1
 There is a driveway on the south side.

Secondary Resource Summary:

There is a modern metal shed ca. 1980s on the east side of the 1 house.

Individual Resource Information

<u>Count</u>	<u>Resource Types</u>	<u>Resource Status</u>
1	Single Dwelling	Contributing
1	Shed	Non-Contributing

Individual Resource Detail Information

Resource Type:	Single Dwelling	Primary Resource?	Yes
Date of Construction:	ca 1900 {Site Visit}	Accessed?	
Architectural Style:	Other	Number of Stories:	1.0
Form:		Condition:	Good
Interior Plan Type:		Threats to Resource:	None Known

Architecture Summary: This is a one-story frame, vernacular side-gable dwelling with a full-facade front porch. End Architecture
 Summary Additions and alterations: End Additions and alterations Interior Description: End Interior Description

**Virginia Department of Historic Resources
Reconnaissance Level Survey**

DHR ID#: 076-0586

Other DHR ID#:

Primary Resource Exterior Component Description:

<u>Component</u>	<u>Comp Type/Form</u>	<u>Material</u>	<u>Material Treatment</u>
Chimneys	Chimneys - Interior	Brick	other
Structural System	Structural System - Frame	Wood	other
Windows	Windows - Sash, Double-Hung	Wood	Windows - 6/6
Foundation	Foundation - Solid/Continuous	Stone	Foundation - Rubble, Random
Porch	Porch - 1-story, 4-bay	Wood	other

Historic Context(s): Domestic

Significance Statement

This early 20th century side-gabled dwelling is a common type for the area and does not appear to be potentially eligible for the National Register of Historic Places.

National Register Eligibility Information (Intensive Level Survey):

National Register Criteria:

Period of Significance:

Level of Significance:

Graphic Media Documentation

<u>DHR Negative #</u>	<u>Photographic Media</u>	<u>Negative Repository</u>	<u>Photo Date</u>	<u>Photographer</u>
	B&W 35mm Photos		March 21, 1996	

Bibliographic Documentation

Cultural Resource Management (CRM) Events

CRM Event # 1,

Cultural Resource Management Event: Survey:Phase I/Reconnaissance

Date of CRM Event: 21, 1996

CRM Person: VCU-ARC

VDHR Project ID # Associated with Event: Virginia Department of Transportation

CRM Event Notes or Comments:

On project numbers: U000-155-V12, PE100 C-500

Bridge Information

Cemetery Information

Ownership Information